Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Attn : Chris Addy

MV : MT Determination

4-Mar-2026

Tema Ship Yard

PAINTING REPORT for DRY DOCKING



Chugoku Marine Paints (Singapore) Pte,Ltd.

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name:	MT Determination
Report Date:	7-Mar-2026
Reference No.:	1
CMP Sales Office:	J-KURE(呉)

Ship Details

Vessel Name		MT Determination
IMO No.		9055711
Owner		T-Tekpor Energy Limited
Ship manager		Chris Addy
Builder		WANATABE SHIPBUILDING - OCHI, JAPAN - 1992
Ship No.		
Kind		OIL TANKER
Size	GT	1,889
	DWT	3,096
	Capacity	
Length	LOA	86.67 m
	LBP	16.00 m
	Breath	13.00 m
	Depth	7.10 m
Delivery		January-1992
Class		NK

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

VESSEL NAME MT Determination

Record of This Drydock

Name of Dockyard	Tema Ship Yard
Date of Drydocking	04-Mar-2026 -> 21-Mar-2026
Dock Interval	60 months *(Last to This time)
Ship Manager	Chris Addy
Superintendent	Chris Addy
Chugoku's Inspector	Craig Hignett

Record of Last Drydock

Name of Dockyard	Tema Dock Yard
Date of Drydocking	13-Mar-2021 -> 13-Mar-2021
Material Used	Unknown
Full Blast date	

Specification (if Chugoku's)

Surface Preparation


SC	Scraping	DS	Disk Sanding	SSB	Spot Swep Blasting	WJB	Water Blasting
FWC	Fresh Water Cleaning	DG	Disk Grinding	SWB	Sweep Blasting		
HPW	High Pressure Water Cleaning	SPB	Spot Blasting	FBL	Full Blasting		

* TU: Touch Up
AO: All Over

			Product Name	D.F.T.	TU/AO
* Painting Area **Flat Bottom**	AC	1st			
		2nd			
		3rd			
* Surface Preparation	AF	1st			
		2nd			
		3rd			
		4th			
* Painting Area **Vertical Bottom**	AC	1st			
		2nd			
		3rd			
* Surface Preparation	AF	1st			
		2nd			
		3rd			
		4th			
* Painting Area **Boottop**	AC	1st			
		2nd			
		3rd			
* Surface Preparation	FC	1st			
		2nd			
		3rd			
		4th			
* Painting Area **Topside**	AC	1st			
		2nd			
		3rd			
* Surface Preparation	FC	1st			
		2nd			
		3rd			
		4th			
* Painting Area	AC	1st			
sqm		2nd			
		3rd			
* Surface Preparation	FC	1st			
		2nd			
		3rd			
		4th			

Coating Breakdown Standards

Figure is used for reference data when deciding corrosion or fouling range of coating film after dry docking.



Abbreviations : N=None S=Slight M=Moderate C=Considerate H=Heavy

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination

Paint Surface Condition

Each condition: N = None, S = Slight, M = Moderate, C = Considerable, H = Heavy
Total evaluation: E = Excellent, G = Good, F = Fair, P = Poor, B = Bad

Fouling

		Each Condition				
		Barnacles	Serpulae	Green Seaweed	Slime	
Sample						Total evaluation
Flat Bottom	P	C	C	M	C	B
	S	C	C	M	C	B
Bilge Keel to L.L.L.	P	C	C	M	C	B
	S	C	C	M	C	B
Stern / Rudder	P	C	C	M	C	B
	S	C	C	M	C	B
Boottop	P	N/A	N/A	N/A	N/A	N/A
	S	N/A	N/A	N/A	N/A	N/A

Remarks

Considering the 5 year specification it was expected to look the way it did with barnacles scattered all over the underwater area of the vessel.

Rusting

		Each condition				Sample image
		Forward	Middle	After	Total evaluation	
Flat Bottom	P	M	M	M	F	
	S	M	M	M	F	
Bilge Keel to L.L.L.	P	M	M	M	F	
	S	M	M	M	F	
Boottop	P	N/A	N/A	N/A	N/A	
	S	N/A	N/A	N/A	N/A	
Topside	P	S	S	S	F	
	S	S	S	S	F	

Remarks

Corrosion caused through poor preparation by not feathering the edges.

Cathodic Protection

System	:	Sacrificial anode
Materials	:	Zinc
Condition	:	Completely wasted
Location	:	Whole Bottom
Renewal	:	36 pieces

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination

Paint Surface Condition

Each condition: N = None S = Slight M = Moderate C = Considerable H = Heavy
Total evaluation: E = Excellent G = Good F = Fair P = Poor B = Bad

Cracking

		Each condition			Total evaluation
		Forward	Middle	After	
Flat Bottom	P	N	N	N	F
	S	N	N	N	F
Bilge Keel to L.L.L.	P	N	N	N	F
	S	N	N	N	F
Boottop	P	N/A	N/A	N/A	N/A
	S	N/A	N/A	N/A	N/A
Topside	P	N	N	N	F
	S	N	N	N	F

Sample image



Remarks

Corrosion caused through poor preparation by not feathering the edges.

Peeling-off

		Each condition			Total evaluation
		Forward	Middle	After	
Flat Bottom	P	S	S	S	F
	S	S	S	S	F
Bilge Keel to L.L.L.	P	S	S	S	F
	S	S	S	S	F
Boottop	P	N/A	N/A	N/A	N/A
	S	N/A	N/A	N/A	N/A
Topside	P	S	S	S	F
	S	S	S	S	F

Sample image



Remarks

Corrosion caused through poor preparation by not feathering the edges.

Blisters

		Each condition			Total evaluation
		Forward	Middle	After	
Flat Bottom	P	N	N	N	F
	S	N	N	N	F
Bilge Keel to L.L.L.	P	N	N	N	F
	S	N	N	N	F
Boottop	P	N/A	N/A	N/A	N/A
	S	N/A	N/A	N/A	N/A
Topside	P	N	N	N	F
	S	N	N	N	F

Sample image




Remarks

Corrosion caused through poor preparation by not feathering the edges.

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination

Paint Film Condition



→	Mechanical damage
XXX	Rusting
CCC	Cracking
VVV	Peeling-off
===	Blisters

Anti-corrosion

Fender was damaged on the middle of Vertical bottom.

Scratches was found on the port and starboard verticle sides due to the vessel rubbing against fender on quay side. Mechanical damage was found by the bow port and starboard due to ancoring.

OOO	Barnacles
+++	Serpulae
###	Green Seaweeds
///	Slime
PPP	Over polish
	Others

Anti-fouling


Slight and moderate green seaweed and slime were observed on Vertical Bottom below draft.

Slight barnacles has 3mm diameter were scattered on the starn of the bottom.

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination

Paint Film Condition



OOO	Power Brush
XXX	Disc Sander
///	Hand Scraping
+++	Sand Sweep, Blasting


Remarks

Sand Sweep 50% of complete underwater area to S.A.1.0 to remove barnacle bases and Sand Blastig 50% of complete underwater area to S.A. 2.0 to treat corroded areas.

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel's Name MT Determination

Paint Film Condition



Mecha.damage	→	メカニカルダメージ
Rusting	XXX	サビ
Cracking	CCC	クラック
Peeling-off	VVV	ハガレ
Blisters	===	フクレ

防食成績 / Anti-corrosion


Barnacles	OOO	フジツボ
Serpulae	+++	セルプラ
Green seaweeds	###	ノリ類
Slime	///	スライム
Over polish	PPP	過度消耗
Others		その他

防汚成績 / Anti-fouling

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel's Name MT Determination

SURFACE PREPARATION



Mecha.damage	→	メカニカルダメージ
Rusting	XXX	サビ
Cracking	CCC	クラック
Peeling-off	VVV	ハガレ
Blisters	===	フクレ

Barnacles	OOO	フジツボ
Serpulae	+++	セルプラ
Green seaweeds	###	ノリ類
Slime	///	スライム
Over polish	PPP	過度消耗

Others		その他


防食成績 / Anti-corrosion

防汚成績 / Anti-fouling

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel's Name MT Determination

SURFACE PREPARATION



Mecha.damage	→	メカニカルダメージ
Rusting	XXX	サビ
Cracking	CCC	クラック
Peeling-off	VVV	ハガレ
Blisters	===	フクレ

防食成績 / Anti-corrosion


Barnacles	OOO	フジツボ
Serpulae	+++	セルプラ
Green seaweeds	###	ノリ類
Slime	///	スライム
Over polish	PPP	過度消耗
Others		その他

防汚成績 / Anti-fouling

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel's Name MT Determination

Paint Film Condition



Mecha.damage	→	メカニカルダメージ
Rusting	XXX	サビ
Cracking	CCC	クラック
Peeling-off	VVV	ハガレ
Blisters	===	フクレ

Barnacles	OOO	フジツボ
Serpulae	+++	セルプラ
Green seaweeds	###	ノリ類
Slime	///	スライム
Over polish	PPP	過度消耗
Others		その他

防食成績 / Anti-corrosion

防汚成績 / Anti-fouling

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination

Hull Paint Specifications in this dock

Vessel's Name	MT Determination
Owner	T-Tekpor Energy Limited
Owner's Supt.	Chris Addy
Name of Dockyard	Tema Ship Yard
Date of Drydocking	04-Mar-2026 -> 21-Mar-2026
Tonnage	3,096 DWT
Type of Vessel	OIL TANKER

＊ TU: Touch Up
AO: All Over

Specification

			Product Name	D.F.T.	TU/AO
＊ Painting Area **Flat Bottom**	AC	1st	UMEGUARD SX, Red Brown	175	AO
		2nd	BANNOH 500 R,	100	AO
		3rd			
＊ SurfFe Preparation HPW:100% SPB:50% SWB:50%	AF	1st	SEAGRANDPRIX 660 HS, Light Brown	100	AO
		2nd			
		3rd			
		4th			
＊ Painting Area **Vertical Bottom**	AC	1st	UMEGUARD SX,	175	AO
		2nd	BANNOH 500 R,	100	AO
		3rd			
＊ SurfFe Preparation HPW:100% SPB:50% SSB:50%	AF	1st	SEAGRANDPRIX 660 HS, L/Brown	100	AO
		2nd	SEAGRANDPRIX 660 HS, Brown	100	AO
		3rd			
		4th			
＊ Painting Area **Boottop**	AC	1st			
		2nd			
		3rd			
＊ SurfFe Preparation	FC	1st			
		2nd			
		3rd			
		4th			
＊ Painting Area **Topside**	AC	1st	UMEGUARD SX,	100	AO
		2nd	UMEGUARD SX,	100	AO
		3rd			
＊ SurfFe Preparation HPW:100% SPB:10% SSB:90%	FC	1st	ACRI 700, Blue	50	AO
		2nd			
		3rd			
		4th			
＊ Painting Area	AC	1st			
		2nd			
		3rd			
＊ SurfFe Preparation	FC	1st			
		2nd			
		3rd			
		4th			

Remarks

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination

Quantity Used

	Products	Packing Size	Quantity	Batch Nos.	Remarks
1	ACRi 700 Finish Blue CS 676	20/D	40	2511369	Code: 0652350020
2	Seagrandprix 660 HS L/Brown	20/D	18	2511600	Code: 0679101020
2	Seagrandprix 660 HS Brown	20/D	15	2511600	Code: 0679100020
3	Umeguard SX Red Brown CS511	20/D	40	2511395	Base; Code: 0388511020
3	Umeguard SX	20/D	40	2511603	Hardener; Code: 0388099099
4	Umeguard SX Grey CS614	20/D	10	2511085	Base; Code: 0388614020
4	Umeguard SX	20/D	10	2511603	Hardener; Code: 0388099099
5	Bannoh 500R Grey	20/D	33	2203747	Base; Code: 36210…
6	Bannoh 500R Grey	20/D	33	2203748	Hardener; Code: 362199
7	Epoxy Thinners	20/D	5	2507114	Code: 0097017020
8	Epoxy Thinners	20/D	5	2203751	Code: 0097017020
9	ACRI Thinners	20/D	10	…	…
10					
11					
12					
13					
14					

General Coments

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination

Hull Coating Daily Schedule

Date	Time	Weather	Temp.	Humidity	Remarks
05/03/2026	12:34				Vessel entered into a wet dock.
	13:00				Commence with Scrapping barnacles and high pressure wash vessel.
06/03/2026	7:00				Commence with Spot Blasting on Topside 10% to S.A. 2.0 and Spot Sweep 70% to S.A. 1.0
	10:00				Inspected by Chugoku Marine Paints Inspector Craig Hignett, Tema Dock Yard contractors and Theodore Tekpor (Owner & Captain) and Companies Superindendent Chris Addy.
07/03/2026	11:00				Continue with Spot Blast 50% to S.A. 2.0 and Spot Sweep to S.A. 1.0 to remove barnacles.
08/03/2026	07:00				Still busy with sand blasting.
09/03/2026	8:00				Inspector to inspect vessel to apply first coat primer of Umeguard SX Red Brown CS 511 to topside and underwater area according to Paint Specification.
					Inspector failed inspection due to underwater area that still had barnacle bases on substrate.
10/03/2026	12:00				Contractors continue with spot sand sweep to remove all barnacle bases.
10/03/2026	7:00			69.90%	Applied 1st coat primer to topside area Umeguard SX Red Brown CS511 @ 156 mic W.F.T.
				69.90%	Applied 1st coat primer to verticle sides and flat bottom area Umeguard SX Red Brown CS511 @ 305 mic W.F.T.
13/03/2026	8:30			57.40%	Applied 2nd coat primer to verticle sides Bannoh 500R Grey @ 175 mic W.F.T.
	14:00			62.30%	Applied 2nd coat primer to topside area Umeguard SX Grey @ 167 mic W.F.T.
14/03/2026	07:30			61.00%	Applied 1st coat antifouling to verticle sides and flat bottom Seagrandprix 660 HS brown @ 196 mic W.F.T.
15/03/2026	8:45			60.40%	Applied 2nd coat antifouling to verticle sides Seagrandprix 660 HS L/Brown @ 196 mic W.F.T.
16/03/2026	7:00			61.10%	Applied finish coat to topside area ACRI 700 Finish Blue CS 676 @ 88 mic W.F.T.
17/03/2026	13:00				Repaint Name, Markings etc on vessel.

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination

Hull Coating Daily Schedule

Date	Time	Weather	Temp.	Humidity	Remarks
18/03/2026					Commenced with Hull Steel inserts for the next few days.
21/03/2026					Completed all steel inserts with hull specification.

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination




GENERAL COMMENTS / REMARKS

Considering the 5 year specification it was expected to look the way it did with barnacles
scattered all over the underwater area of the vessel.
Corrosion caused through poor preparation by not feathering the edges.

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination



Photographic log showing – Vessel condition on arrival

05/03/2026 MT Determination condition on arrival Commence with washing and scrapping off barnacles.	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination



Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination


Photographic log showing – Vessel condition on arrival

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination



Photographic log showing – Blasting

06/03/2026 Commence with Blasting.	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination




Photographic log showing – Blasting

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination


Photographic log showing –

12/03/2026 Applied 1st coat primer Umeguard SX Red Brown CS511 @ 156 mic W.F.T. to Topside and Underwater Area.	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination



Photographic log showing – Painting

10/03/2026 Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination



Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination


Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination


Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination



Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination



Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination



Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination




Photographic log showing –

Ditto	
13/03/2026 Apply 2nd coat primer Bannoh 500R Grey CS614 @ 305 mic W.F.T. to underwater area.	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination

Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination

Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination



Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination

Photographic log showing –

13/03/2026 Applied 2nd coat primer to topside area Umeguard SX Grey @ 167 mic W.F.T.	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination

Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination


Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination


Photographic log showing –

14/03/2026 Applied 1st coat antifouling to underwater area Seagrandprix 660 HS brown to Verticle bottom and flat bottom @ 196 mic W.F.T.	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination




Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination




Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination




Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination



Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination



Photographic log showing –

Ditto	
Ditto	
16/03/2026 Applied finish coat to topside area ACRI 700 Finish Blue CS 676 @ 88 mic W.F.T.	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination




Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination




Photographic log showing –

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination



Photographic log showing –

Ditto	
Ditto	
21/03/2026 Repainted Name, Markings etc. Vessel completed	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination



Photographic log showing – Complete Vessel

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination


Photographic log showing – Complete Vessel

Ditto	
Ditto	
Ditto	

Chugoku Marine Paints (Singapore) Pte,Ltd.
22 Tuas Street, Singapore
TEL:65-6861-6500 / FAX:65-6861-3002

Vessel Name: MT Determination

Photographic log showing – Complete Vessel

Ditto	
Ditto	
Ditto	